


**LEACHATE COLLECTION WELLS
INTERIM OM&M MONITORING AND BAILING DATA SHEET
WASTE DISPOSAL, INC. SUPERFUND SITE**

DATE: ¹⁶ November 9, 2006


TECHNICIAN NAME: HARKENSCHIED

TECHNICIAN SIGNATURE 

WELL ID	BOTTOM OF WELL AFTER CONSTRUCT-ED [TOTAL DEPTH] (ft)	MEASURED BOTTOM OF WELL [TOTAL DEPTH] (ft)	GAUGING TIME		DEPTH TO LIQUID (ft)						HEIGHT OF LIQUID COLUMN (ft)		VOLUME OF LIQUID REMOVED (gallons)	COMMENTS
			Start	Finish	Start			Finish			Start	Finish		
					1 st Rdg.	2 nd Rdg.	3 rd Rdg.	1 st Rdg.	2 nd Rdg.	3 rd Rdg.				
LC-1	22.25	22.23	1400	1410	18.15	18.15	18.15	21.76	21.76	21.76				
LC-2	21.90	21.90	1421	1433	12.69	12.69	12.69	21.23	21.23	21.23				
LC-3	22.20													
LC-4	21.90	21.90	1445	1500	11.47	11.47	11.47	21.30	21.30	21.30				

W:\Interim_OM+M\LeachateCollectionWells\WorkPlan+FieldForms\November2006\Nov906LC-WellsM&B(YF1).doc

**LEACHATE COLLECTION WELLS
INTERIM OM&M INSPECTION SHEET
WASTE DISPOSAL, INC. SUPERFUND SITE**

INSPECTOR'S NAME	INSPECTOR'S SIGNATURE	INSPECTION TIME	INSPECTION DATE
HARKENSCHIED		1400	November 9 th , 2006

ITEM OF POTENTIAL CONCERN	CONDITIONS OBSERVED				COMMENTS	CHECK (•) BELOW WHEN COMPLETED
	WELL ID LC-1	WELL ID LC-2	WELL ID LC-3	WELL ID LC-4		
Wellhead (well box, cover, gasket, concrete)	OK	OK		OK		✓✓✓
Well Casing and Cap/Plug	OK	OK		OK		✓✓✓
Liquid Present in Well Box	NO	NO		NO		✓✓✓
Other:						
Other:						
Other:						

W:\Interim_OM+M\LeachateCollectionWells\WorkPlan+FieldForms\November2006\Nov906LC-WellsInspection(YF).doc

T

TRC

Customer-Focused Solutions

DAILY FIELD REPORT
WASTE DISPOSAL, INC
SANTA FE SPRINGS, CALIFORNIA

FIGURE J.1